

```

1
2
3
4 #CM Der Trick ist : tcc -c -ml -B timer.c , wenn make abbricht
5
6
7
8 CC = tcc
9 #CC = bcc32
10
11 TIMER = ZEN_TIMER
12 TIMER = CTC
13
14 !if $(CC) == tcc
15
16 MDL = 1
17 ASM = tasm
18 LINK = tlink
19 AFLAGS = /ml
20 LIBDIR = c:\turboc3\lib
21 CFLAGS = -m$(MDL)
22 CFLAGS2 = -m$(MDL)
23 LDFLAGS = /L$(LIBDIR)
24 C0 = $(LIBDIR)\c0$(MDL)
25 LIBS = c$(MDL).lib math$(MDL).lib fp87.lib
26
27 !else
28
29 LIBDIR = d:\bcc55\lib
30 ASM = tasm
31 AFLAGS = /ml /D_WIN32
32 CFLAGS = -D_WIN32
33 LINK = ilink32
34 LDFLAGS = /L$(LIBDIR)
35 C0 = c0d32
36 LIBS = cw32.lib import32.lib uuid.lib
37
38 !endif
39
40 OBJS = hw.obj setpins.obj delays.obj console.obj filefunc.obj \
41       config.obj buffuncs.obj timer.obj
42
43 .c.obj:
44     $(CC) -c $(CFLAGS) $<
45
46 .asm.obj:
47     $(ASM) $(AFLAGS) $<
48
49 goal:    all03.exe eep3.exe mpu4.exe mpu5.exe mpu6.exe pic16.exe pgm89.exe tbprom.exe
50
51 pic16.exe:  pic16.c timer.obj
52     $(CC) $(CFLAGS2) pic16.c timer.obj
53
54 mpu4.exe:   mpu4.c all03.h all03.lib
55     $(CC) $(CFLAGS2) mpu4.c all03.lib
56
57 mpu5.exe:   mpu5.c all03.h all03.lib
58     $(CC) $(CFLAGS2) mpu5.c all03.lib
59
60 all03.exe:  all03.c all03.h all03.lib
61     $(CC) $(CFLAGS2) all03.c all03.lib
62
63 eep3.exe:   eep3.c all03.h all03.lib
64     $(CC) $(CFLAGS2) eep3.c all03.lib
65
66 pgm89.exe:  pgm89.c all03.h all03.lib
67     $(CC) $(CFLAGS) pgm89.c all03.lib
68
69 mpu6.exe:   mpu6.c all03.h all03.lib
70     $(CC) $(CFLAGS) mpu6.c all03.lib

```

```
71
72  tbprom.exe: tbprom.c all03.h all03.lib
73      $(CC) $(CFLAGS2) tbprom.c all03.lib
74
75
76
77  all03.lib: $(OBJS)
78      -DEL all03.lib
79      tlib all03 +hw +setpins +delays +timer +console +filefunc +config +buffuncs
80
81  hw.obj:      hw.c all03.h
82  delays.obj:  delays.asm
83  console.obj: console.c all03.h
84  setpins.obj: setpins.c all03.h
85  filefunc.obj: filefunc.c all03.h
86  config.obj:  config.c all03.h
87  buffuncs.obj: buffuncs.c all03.h
88  timer.obj:   timer.c timer.h
89
90
```